

Modeling and Simulation

Time Allowed: 3 Hrs. 2nd Year Students.

Total Marks: 16 / 1 / 2013

[1]

A. Define

- I. Controllable system
- II. Observable system
- III. Regulator Poles
- IV. Eigenvalues
- B. Consider that a third-order system has the coefficient matrices

$$A = \begin{bmatrix} 1 & 2 & -1 \\ 0 & 1 & 0 \\ 1 & -4 & 3 \end{bmatrix} \qquad B = \begin{bmatrix} 0 \\ 0 \\ 1 \end{bmatrix}$$

Check system controllability?

C. For the system that have

$$A = \begin{bmatrix} -2 & 0 \\ 0 & -1 \end{bmatrix} \quad B = \begin{bmatrix} 3 \\ 1 \end{bmatrix} \qquad C = \begin{bmatrix} 1 & 0 \end{bmatrix}$$

Check system Observability?

[2]

- A. Find out if the matrix $\begin{bmatrix} -e^{-t} & 0 \\ 0 & 1 e^{-t} \end{bmatrix}$ can
 - be state-transition matrix
- B. For the spring-mass-damper system shown below. The state equations are

$$\begin{bmatrix} \dot{x}_1 \\ \dot{x}_2 \end{bmatrix} = \begin{bmatrix} 0 & 1 \\ -\frac{K}{m} & -\frac{C}{m} \end{bmatrix} \begin{bmatrix} x_1 \\ x_2 \end{bmatrix} + \begin{bmatrix} 0 \\ \frac{1}{m} \end{bmatrix} u$$


Given: m = 1 kg, C = 3 Ns/m, K = 2 N/m, u(t) = 0. Evaluate,

- The characteristic equation, its roots
- The transition matrices $\varphi(s)$ and $\varphi(t)$
- The transient response of the state variables from the set of initial conditions $y(0) = 1.0, \dot{y}(0) = 0$



- A. Define
 - State observer
 - II. Pole Placement
- B. Consider a system defined by

$$\dot{X} = AX + BU$$



Where

$$A = \begin{bmatrix} 0 & 1 \\ -2 & -3 \end{bmatrix}, \qquad B = \begin{bmatrix} 0 \\ 2 \end{bmatrix}, \qquad C = \begin{bmatrix} 1 & 0 \end{bmatrix}$$

It is desired to have egenvalues at -3 and -5 by using state-feedback control u = -Kx. Determine the state-feedback gain matrix

Use MATLAB to compute and plot the impulse and step responses of the state-space model

$$A = \begin{bmatrix} -2 & -2.5 & -0.5 \\ 1 & 0 & 0 \\ 0 & 1 & 0 \end{bmatrix}, \qquad B = \begin{bmatrix} 1 \\ 0 \\ 0 \end{bmatrix}$$
$$C = \begin{bmatrix} 0 & 1.5 & 1 \end{bmatrix}, \qquad D = \begin{bmatrix} 0 \end{bmatrix}$$

Then simulate and plot the state response $x(t) = [x_1(t) \ x_2(t) \ x_3(t)]^T$ when the input is $u(t) = \begin{cases} 2 & 0 \le t \le 2 \\ 0.5 & t \ge 2 \end{cases}$ and the initial condition is $x(0) = [1 \ 0 \ 2]^T$

[5] Consider the system defined by

$$\dot{X} = AX + BU$$

Where

$$A = \begin{bmatrix} 0 & 1 & 0 \\ 0 & 0 & 1 \\ -1 & -5 & -6 \end{bmatrix} \quad B = \begin{bmatrix} 0 \\ 0 \\ 1 \end{bmatrix}$$

By using the state feedback control u=-Kx, It is desired to have the closed loop ploes at $s=-2\pm j4$ and s=-10. Determine the state feedback gain matrix using MATLAB

[6]

Consider a system defined by

$$\dot{X} = AX + BU$$
$$Y = CX$$

Where

$$A = \begin{bmatrix} -1 & 0 & 1 \\ 1 & -2 & 0 \\ 0 & 0 & -3 \end{bmatrix}, \qquad B = \begin{bmatrix} 0 \\ 0 \\ 1 \end{bmatrix}, \qquad C = \begin{bmatrix} 1 & 1 & 0 \end{bmatrix}$$

Transform the system into

- Controllable canconical form
- Draw state diagram of Controllable canconical form
- Observable canonical form
- Find eigenvalues

BEST WISHES

Dr. Mostafa A. El-hosseini www.melhosseini.net

2